

Metal Forming – BSc 2024/25-1


Sheet Metal Forming

Deep drawing

Introduction

Definition of sheet metal: the size in one direction is much smaller than in the other two.

Deep drawing is the forming of sheet blanks into hollow parts.





- 1 drawing punch
- 2 blank holder
- 3 drawing ring
- 4 container
- 5 base plate
- 6 ejector

Products



Deformation - stress


Role of tangential stress
(may cause wrinkling)



stock


product

Deformation - stress



Complex inhomogeneous stress and strain state exists.

Role of blank holder



If $D/s < 20$ (thick sheet),
no blank holder is needed.


Too low blank holder pressure
→ wrinkling



Too high blank holder pressure
→ crack




Defects



Wrinkling



Wall wrinkling




Crack



Earing


Deep drawing without blank holder

Deep drawing with **tractrix** curved die without blank holder:





A tractrix is a curve for which the section of the tangent between the point of contact and the y-axis is constant.

Deep drawing with heated die




For materials with **high strength** and/or with **low deep drawability**

Multistep deep drawing – second step




Multistep deep drawing – reverse redrawing

a)



b)




Blank geometry – axisymmetric part

Assuming constant surface area:

$$A = \frac{D^2 \pi}{4} = \frac{d_m^2 \pi}{4} + d_m \pi (h_m + h')$$

$$D = \sqrt{d_m^2 + 4d_m (h_m + h')}$$



If the workpiece consist of simple shapes
($A_1, A_2 \dots A_n$)

$$A = \frac{D^2 \pi}{4} = \sum_{i=1}^n A_i, \quad D = \sqrt{\frac{4}{\pi} \sum_{i=1}^n A_i}$$

$$h/d = 0,5..4 \text{ mm}, \quad h = 20..300 \text{ mm}, \\ h' = 2-12 \text{ mm}$$

Technology planning

Due to the material and geometric limit, not any geometry can be done in one step; The drawn cup can be formed further in other deep drawing steps. For each steps a draw ratio $m_t = d_n / d_{n-1}$ can be defined: the ratio of the diameters in the n^{th} and $n-1^{\text{th}}$ step.

Its maximal values is material dependent, but $m = 0.55-0.6$ for the first step (forming a cup from planar blank) and $m_t = 0.75-0.85$ for the further drawing steps.

The material is characterized by a maximum total draw ratio of q_{max} .
(If q_{max} is smaller, the drawability is better!)

Blank for cylindrical pieces

- 1) Assuming that the **surface area is constant**;
the surface area of the final geometry is calculated.
- 2) If the material is **anisotropic**, the **cup height is increased with 5-15%** depending on the anisotropy value of the material
- 3) The blank diameter D is calculated.

Technology planning

Knowing the maximal drawing ratio, the first diameter is $d_1 = mD$, and the further drawing diameters are: $d_2 = m_t d_1 = m_t mD$, $d_3 = m_t d_2 = m_t^2 mD \dots$

Diameter after n drawing: $d_n = m_t^{n-1} mD$

If D and d_n are known, then the **number of** necessary drawing **steps**:

$$n = \frac{\ln d_n - \ln(mD)}{\ln m_t} + 1$$


The resulted value must be **rounded up**. Therefore, it is useful to continuously increase a bit the ratios from the first step to distribute the difference.

The number of drawing steps to the first annealing:


$$k = \frac{\ln(1 - q_{max}) - \ln m}{\ln m_t} + 1$$

The resulted value must be **rounded down**.



Related technique - ironing







Multistep redraw with ironing




Die design examples



Die design examples




Hydro-mechanical deep drawing



Example

Calculate the total number of drawing steps and the number of steps to the first annealing:



$$d_m = 30 \text{ mm}$$

$$h = 70 \text{ mm}$$

$$s = 2 \text{ mm}$$

$$D = ???$$

$$n = ???$$

$$\text{annealing } ??? \quad (q_{\max} = 0.5)$$

$$(m = 0.6)$$

$$(m_t = 0.85)$$

Thank you for your attention!